



UNIT INFORMATION:

Type : PM ☐ REPAIR ☒ RENTAL ☐ TUV ☐ ABS ☐ ACC ☐

UNIT NO.	AIRCON UNIT - NPCO HEAD OFFICE	DATE OPEN	2023-02-21	PREVIOUS HR METER	
EQUIPMENT	Motorized	PLAT NO.	N/A	PRESENT HR METER	
MODEL	N/A	SERIAL NO.	N/A	LAST PM DATE	0000-00-00
CHASSIS NO.	N/A	YEAR	2019	LAST VISIT TO SHOP	
WORKORDERID	NPCOWO2289	CHECKIN DATETIME	2023-02-21 12:43:00	CHECKOUT DATETIME	2023-02-21 12:43:00
TOTAL CHECKTIME	0:0				

CUSTOMER INFORMATION

COMPANY NAME	NPCO	PRN NO.	NP187
REPRESENTATIVE NAME	KHALID AL-RUSAINI - MGR FACIL/GSE MAINTENANCE	SIGNATURE	

PROBLEM DISCUSSION

OIL/WATER LEAK NOISY ☐ ENGINE A/C PROBLEM ☐ TIRE PROBLEM ☐ PAINT/BODY ☐
 DAMAGE UPHOLSTERY ☐ BREAK DOWN ☐ RENTAL OF GPU ☐ ELECTRICAL PROBLEM ☐
 RENTAL OF PAX STEP ☐ ACCIDENT ☐ RENTAL OF FORKLIFT ☐ OTHER PROBLEMS ☒

DEFECTIVE CONDENSER FAN MOTOR / CHECK REFRIGERANT

OPEND BY

NAME	JOGEN MAHINAY - MECHANIC
SIGNATURE	
PRN	NP134
DATE	2023-02-21

CLOSED BY

NAME	
SIGNATURE	
PRN	0000-00-00
DATE	08-3-2023

TERM AND CONDITION

- All work to be done will be based on the quotation. Any additional work and findings during disassembly and inspection will be an added charge.
- The inspection schedule must be provided a minimum of two days before.
- Friday/Saturday or National holiday rates are chargeable at the overtime rate plus 20%.
- A P.O must be issued before the commencement of services.
- Any major repair services completed must be evaluated and accepted by the customer before the equipment is released.
- Customers have to provide the necessary technical manuals in conjunction with the equipment under repair.
- All information obtained or created during the performance of inspection activities shall remain confidential, except as required by law.
- VAT will be charged on all invoices following government rules and regulations.
- All major repairs, such as engine, transmission, and power train overhauls, have a 30-day warranty period from the date of release, and acceptance of the unit. No warranty is provided for corrective maintenance, preventive maintenance, electrical, and other minor repairs.

CONDITIONS GOVERNING THE PROVISION OF SERVICE

- The owner agrees with full knowledge that the required services mentioned overleaf are provided on accommodation and/or reciprocal basis, and NPCO, its employees, or agents will not be responsible or liable for any loss or damage to the owner or any person, whether or not such damage is caused due to the negligence of NPCO, its employees, or its agents, except for gross negligence or willful misconduct of NPCO, its employees, its servants, or its agents. The owner hereby also agrees to absolve NPCO, its employees, its servants, and its agents from and against all claims for the cost of losses, damages, and legal proceedings, including consequential losses arising from or against death or injury to persons (or to any person considered as the third party), including but not limited to passengers and the owner's employees, and also those arising from the loss or damage of property belonging to a person (or to

Technician's Report / Job Done (Please write clearly and do not use liquid eraser; use separate sheet if necessary.)

M.CODE	DATE	HRS	JOB DONE
NP134	21/2/23		TROUBLESHOOT AND CHARGE REFRIGERANT FOR
NP199	21/2/23		ALL A/C UNIT IN HEAD OFFICE. FOUND PROCUR-
			MENT OFFICE A/C BLOWING HOT AIR, AND HR
			OFFICE, CONDENSER FAN MOTOR DEFECTIVE.
NP134	28/2/23		REPLACE 2 EA DEFECTIVE FAN MOTOR OF
NP199	28/2/23		HR OFFICE AND CHARGE REFRIGERANT.
			CHARGE REFRIGERANT ALSO IN PROCUREMENT
			OFFICE.
NP134	2/3/23		REPLACE 2 EA DEFECTIVE CONDENSER FAN MOTOR
NP199	2/3/23		IN WHOLE WAY OF HEAD OFFICE AND CHARGE
			REFRIGERANT.
NP134	7/3/23		TROUBLESHOOT OF A/C BLOWING HOT AIR, CHARGE
NP199	7/3/23		REFRIGERANT. CONTINUED RUN A/C FOR OBSER-
			VATION. NO PROBLEM FOUND. ALL UNIT NOW
			IS BACK TO SERVICE.
			* NOTE: ALL UNIT NEED PRESSURIZED CLEAN
			BY WATER (CONDENSER SIDE)

[illegible]